



SAMCON

Prozessleittechnik GmbH


Assembly Instruction

product: CMB-TNXCD
author: S. Weber
date: June 26, 2018
update: January 25, 2021
doc ID: 180626-PZUMA-SW-CMB-TNXCD_assembly
instruction_rev.01.idw
passing:




INTRO

1



What you need:	
Wrench	13mm
Torque wrench	13mm



ATTENTION:


Please be careful when working at heights !



3

6

*Not-included fastening parts required!
Threaded bolts M12
for individual ceiling
mount*



5


4

2

Table of content


obj.	qty.	part	material
1	1	CMB TNXCD part I	stainless steel
2	1	CMB TNXCD part II	stainless steel
3	5	Treaded bolt ISO 4017 - M8 x 16	stainless steel
4	10	Washer DIN 125 - A 8,4	stainless steel
5	5	Treaded bolt ISO 4017 - M8 x 12	stainless steel
6	1	safety wire 3 x 500mm	stainless steel

1




Fix to ceiling !

2




tightening: 15Nm


3



4






5



tightening: 15Nm

6





Note:
For more information see
other assembly instructions!



SAMCON

Prozessleittechnik GmbH

